

Upper Hoke Meadow Restoration Design RFP  
Attachment 2. Photographs of project area



Dried out portion of meadow, disconnected from incised stream channel.

Upper Hoke Meadow Restoration Design RFP  
Attachment 2. Photographs of project area



Existing stream channel. A series of rock and cyclone fence gabions were placed in the stream channel at some time in the past, possibly as a strategy to arrest erosion.



Upper Hoke Meadow Restoration Design RFP  
Attachment 2. Photographs of project area



Aspen stand, and some evidence of past ditching. Aspen restoration is one of the objectives of the project.



Upper Hoke Meadow Restoration Design RFP  
Attachment 2. Photographs of project area



Tributary drainage near upstream end of meadow. Substantial sediment appears to come out of this drainage.



Upper Hoke Meadow Restoration Design RFP  
Attachment 2. Photographs of project area



Example of erosion in contributing watershed.



Upper Hoke Meadow Restoration Design RFP  
Attachment 2. Photographs of project area



Road crossing near top of meadow on Forest Service Road 72.

Upper Hoke Meadow Restoration Design RFP  
Attachment 2. Photographs of project area



Portions of the existing channel support vigorous wet meadow vegetation.